MATERIAL SAFETY DATA SHEET

LaMOTTE COMPANY
PO BOX 329 - CHESTERTOWN - MARYLAND - 21620
TELEPHONE # FOR INFORMATION 410-778-3100

24 Hour Emergency Number (CHEM-TEL) 800-255-3924

1. PRODUCT IDENTIFICATION

Acid Extracting Solution *Code Nr.* **6361**

2. HAZARDOUS INGREDIENTS

	NAME	CAS #	TSCA #	%	PEL	TLV
^	Hydrochloric Acid	7647-01-0		<3	C 7 mg/cubic m	C 5 ppm
^	Sulfuric Acid	7664-93-9		<2	1 mg/cubic m	1 mg/cubic m

3. NON-HAZARDOUS INGREDIENTS EXCEPT WATER (7732-18-5)

NAME	CAS #	%
Water to 100%		

4. PHYSICAL DATA

Appearance: Clear Colorless Liquid

Solubility in Water: Soluble	*Odor:* Slight	*Boiling Point:* > 100 deg C	*Melt. Point:* N/A
Vapor Pressure: <17 @ 20 deg C	*Vapor Density:* >1 (Air=1)	*pH:* <1	

5. FIRE AND EXPLOSION DATA

Flash Point (method used) N/A | *Flammable Limit: LEL:* N/A | *UEL:* N/A

Extinguishing Media: Not a fire hazard

HMIS Hazard: Health - 2 *Flammability -* 0 *Reactivity -* 1 *Scale: 4 = Extreme, 3 = High, 2 = Moderate, 1 = Slight, 0 = Least*

Special Fire Fighting Procedures:
N/A

Unusual Fire & Explosion Hazard:
Contact with metals may produce flammable hydrogen gas.

6. REACTIVITY DATA

Stability:
☒ *Stable*
☐ *Unstable*

Conditions to avoid: Heat

Incompatibility (Materials to avoid):
Alkalies, metals

Hazardous Decomposition Products: HCl gas, SOx, hydrogen gas

7. HEALTH HAZARD DATA

Toxicity: orl rat LD50: 2140 mg/kg for sulfuric acid, concentrated

Primary Route of Entry: ☐ *Inhalation* ☒ *Skin* ☒ *Ingestion* ☐ *N/A*

Carcinogenicity: ☒ *None* ☐ *NTP* ☐ *OSHA* ☐ *IARC*

Other Health Related Comments:

Target Organs: Corrosive to all body parts,

Signs and symptoms of exposure:
May be irritating to eyes, nose and skin. Harmful if swallowed.

Medical Condition Aggravated by Exposure: N/A

8. EMERGENCY FIRST AID PROCEDURES

Eye Contact: Flush thoroughly with water for 15 minutes. Consult a physician.

Ingestion: Rinse out mouth. Drink plenty of water. Consult physician.

Inhalation:
Remove to fresh air.

Skin Contact:
Flush thoroughly with water. Remove affected clothing and wash skin with soap and water.

9. SPILL AND DISPOSAL PROCEDURES

Spill and Leak:
Cover spill with sodium bicarbonate. Scoop up neutralized slurry and wash down drain with excess water.

Disposal:
Add slowly to a solution of soda ash and calcium hydroxide. Pour neutralized solution down drain with excess water. Dispose according to federal, state and local regulations.

10. PRECAUTIONARY MEASURES

In Handling: ☒ *Gloves* ☒ *Eye Protection* ☐ *N/A* ☒ *Other:* Lab Coat

Ventilation ☒ *Normal* ☐ *Mechanical* ☐ *Respiratory Protection*

Work/Hygienic Practices: Avoid contact with eyes, skin and clothing.

11. SPECIAL PRECAUTIONS

N/A

DATE: 8/10/02

The above information is believed to be correct but does not claim to be all inclusive and should be used only as a guide.

^ This is a toxic chemical subject to reporting requirements of section 313 of EPCRA and 40CFR372.